

STATEMENT OF PASSING OVER INFORMATION:
This information has been supplied to us by a third party.
Accordingly the Vendor and Austar Realty Limited are merely passing over this information as supplied to us by others. While we have passed on this information supplied by a third party, we have not checked, audited, or reviewed the records or documents and therefore to the maximum extent permitted by law neither the Vendor nor Austar Realty Limited or any of its salespersons or employees accept any responsibility for the accuracy of the materials, intending purchasers are advised to conduct their own investigation.

Ph: 0800 766 463 info@buildinginspect.co.nz www.buildinginspect.co.nz Registration Nu NZIBI 031

Pre-purchase HOUSE inspections

BULLET POINT INSPECTION

Inspection 8682

Customer Graham Biddle


Property Address 3 Boylon Road, Titirangi

Date 01/07/2024



The purpose of this inspection at the above address was to verify the standard of construction of deck on east and north sides of dwelling.

On inspection of the deck area, the deck was found to have been constructed to a high level of workmanship and constructed to the standards required at time of construction i.e. Correct mechanical fixings, handrail height and all relevant fixings. See photos below:














The purpose of this inspection at the above address was to verify the standard of construction of deck on east and north sides of dwelling.

On inspection of the deck area, the deck was found to have been constructed to a high level of workmanship and constructed to the standards required at time of construction i.e. Correct mechanical fixings, handrail height and all relevant fixings. See photos below:































Inspection Date: 01/07/2024 Inspector: Damon Schubert 021-878491

Bryan Schubert Company Director

B.S. Seletato